




KCIA AIRPORT ADVISORY

DATE: May 15, 2003

TO: King County International Airport Tenants
distributed by e-mail and fax

FROM: 
Robert I. Burke, Airport Director

SUBJECT: Runway 13R/31L Partial Closure - May 17 (Saturday)

KCIA will be "grooving" the section of Runway 13R/31L that was repaved at the end of April. This area is located between the B3 and B4 taxiway intersections.

The grooving is scheduled for **May 17, 2003 - SATURDAY from 0830 - 2030 local time**. This project will not be weather dependent. It will require **closing the north 5000 feet of RWY 13R**. Therefore, if 13R is active, there will be 5000 feet for arrival and departure. If 31L is active, there will be 5000 feet for departure and 4200 feet for arrival. Additionally, the **B3 and B2 taxiway intersections will be closed**. Be sure to **CHECK NOTAMs** for any changes.

We apologize for any inconvenience the repairs to the main runway have caused over the past few weekends, but we are sure you will be pleased with the improved runway surface.

ERROR INFORMATION

[* 6]9p7633964
[* 9]8p947395p6142381807
[*071]8p947395p5098840534
[*072]9p7637761
[*073]9p2533952458
[*074]9p6551454
[*005]9p7318558
[*013]9p7670755
[*014]9p2535291081
[*024]9p4333619
[*053]9p7671600
[*054]9p7644001
[*063]9p7637124
[*068]9p4252265314
[*075]9p6762645

MENTE AVAITION
AIRNET
EXECUTIVE FLIGHT
OTTER CORP
AIRBORNE EXPRESS
BOEING
AIRLIFT NW
AVOLO
B&B AIRCRAFT
GENISIS AIRCRAFT
WA AIR NATL GRD
WA AERO
AMERICAN FLYERS
FBL JET
NATIONAL CHARTER

**KCLIA AIRPORT ADVISORY**

DATE: May 15, 2003

TO: King County International Airport Tenants
distributed by e-mail and fax

FROM: 
Robert I. Burke, Airport Director

SUBJECT: Runway 13R/31L Partial Closure - May 17 (Saturday)

KCIA will be "grooving" the section of Runway 13R/31L that was repaved at the end of April. This area is located between the B3 and B4 taxiway intersections.

The grooving is scheduled for **May 17, 2003 - SATURDAY from 0830 - 2030 local time**. This project will not be weather dependent. It will require **closing the north 5000 feet of RWY 13R**. Therefore, if 13R is active, there will be 5000 feet for arrival and departure. If 31L is active, there will be 5000 feet for departure and 4200 feet for arrival. Additionally, the **B3 and B2 taxiway intersections will be closed**. Be sure to **CHECK NOTAMs** for any changes.

We apologize for any inconvenience the repairs to the main runway have caused over the past few weekends, but we are sure you will be pleased with the improved runway surface.

*** MULTI TX/RX REPORT ***

TX/RX NO	3211	
PGS.	1	
TX/RX INCOMPLETE	[*017]9p7675440	BFI AVIATION
	[*021]9p7632590	FEDEX
	[*038]9p7672549	NW EXEC AIR
	[*040]9p7638421	RAYTHEON AIRCRAF
	[*046]9p7860483	TC AVIATION
	[*067]9p6220837	ROLING FLIGHT
	[*070]9p6550667P	DEPT OF DEFENSE
TRANSACTION OK	[*003]9p7621223	AIR TRANSPORT
	[*004]9p7630381	AIRBORNE EXPRESS
	[*006]9p7626357	AIRPAC AIRLINES
	[*007]9p7632036	AMERICAN AVIONIC
	[*008]9p7636239	AMERIFLIGHT
	[*009]9p7621158	AVIATION PARTNER
	[*010]9p7633428	AVIATION BOOK CO
	[*011]9p7647112	AVIATION TRAINIG
	[*012]9p7633428	AVIATOR STORE
	[*015]9p7620611	BAX GLOBAL
	[*016]9p6555116	BOEING CO
	[*018]9p7648124	CALIBER INSPECT
	[*019]9p7674018	CLASSIC HELICOPT
	[*022]9p7680888	FLIGHTCENTER
	[*023]9p7679333	GALVIN FLYING
	[*025]9p7689700	GUIDO PERLA & AS
	[*026]9p7689458	HELIJET
	[*027]9p7679333	KING BROADCASTIN
	[*028]9p7641904	KC JETCENTER
	[*029]63838	EMERGENCY MGMNT
	[*030]60514	SAFETY & CLAIMS
	[*031]64271	GUARDIAN ONE
	[*032]64271	SPECIAL OPS
	[*033]9p7626046	LINDEAN AIRCRAFT
	[*035]9p7641312	NATIONAL AVIATIO
	[*036]9p7681715	NORDSTROM
	[*037]8p120329p6042782608	N VANCOUVER AIR
	[*039]9p7634837	PISTOL CREEK FIN
	[*043]9p7623542	SEATTLE JET STRM
	[*044]9p7633320	SERVICE GROUP
	[*045]9p7630381	SOUND AERIAL SVY
	[*047]9p7641986	TAG AVIATION
	[*048]9p7674920	UPS
	[*049]9p5536851	US CUSTOMS
	[*050]9p5530190	US IMMIGRATION
	[*051]9p7643862	VALKERIE CORP
	[*052]9p7644760	WA AUDIOLOGY
	[*055]9p7681947	WEST ISLE AIR
	[*056]9p7674539	WESTERN METALS
	[*057]9p7679464	WINGSALOFT
	[*058]9p7645707	MUS OF FLIGHT
	[*059]8p120329p6042735301	HELIJET
	[*060]8p120329p3602930517	WEST ISLE AIR
	[*061]9p7630381	AIR TRANSPORT
	[*062]9p7635156	S SEATTLE CC
	[*064]9p7622997	DUNCAN AVIONICS
	[*065]9p7677662	GALVIN-MAIT BLDG


*** TX REPORT ***

TRANSMISSION OK

TX/RX NO 3212
CONNECTION TEL 95211865
SUBADDRESS
CONNECTION ID AIRLIFT NORTHWES
ST. TIME 05/16 07:23
USAGE T 01'24
PGS. SENT 1
RESULT OK



KCLIA AIRPORT ADVISORY

DATE: May 15, 2003
TO: King County International Airport Tenants
distributed by e-mail and fax
FROM: 
Robert I. Burke, Airport Director
SUBJECT: Runway 13R/31L Partial Closure - May 17 (Saturday)

KCLIA will be "grooving" the section of Runway 13R/31L that was repaved at the end of April. This area is located between the B3 and B4 taxiway intersections.

The grooving is scheduled for **May 17, 2003 - SATURDAY from 0830 - 2030 local time**. This project will not be weather dependent. It will require **closing the north 5000 feet of RWY 13R**. Therefore, if 13R is active, there will be 5000 feet for arrival and departure. If 31L is active, there will be 5000 feet for departure and 4200 feet for arrival. Additionally, the **B3 and B2 taxiway intersections will be closed**. Be sure to **CHECK NOTAMs** for any changes.

We apologize for any inconvenience the repairs to the main runway have caused over the past few weekends, but we are sure you will be pleased with the improved runway surface.

*** TX REPORT ***

TRANSMISSION OK

TX/RX NO 3217
CONNECTION TEL 97625481
SUBADDRESS
CONNECTION ID
ST. TIME 05/16 07:31
USAGE T 00'51
PGS. SENT 1
RESULT OK



KCIA AIRPORT ADVISORY

DATE: May 15, 2003

TO: King County International Airport Tenants
distributed by e-mail and fax

FROM: 
Robert I. Burke, Airport Director

SUBJECT: Runway 13R/31L Partial Closure - May 17 (Saturday)

KCIA will be "grooving" the section of Runway 13R/31L that was repaved at the end of April. This area is located between the B3 and B4 taxiway intersections.

The grooving is scheduled for **May 17, 2003 - SATURDAY from 0830 - 2030 local time**. This project will not be weather dependent. It will require **closing the north 5000 feet of RWY 13R**. Therefore, if 13R is active, there will be 5000 feet for arrival and departure. If 31L is active, there will be 5000 feet for departure and 4200 feet for arrival. Additionally, the **B3 and B2 taxiway intersections will be closed**. Be sure to **CHECK NOTAMs** for any changes.

We apologize for any inconvenience the repairs to the main runway have caused over the past few weekends, but we are sure you will be pleased with

*** TX REPORT ***

TRANSMISSION OK

TX/RX NO 3216
CONNECTION TEL 97674047
SUBADDRESS
CONNECTION ID
ST. TIME 05/16 07:30
USAGE T 00'52
PGS. SENT 1
RESULT OK



KCIA AIRPORT ADVISORY

DATE: May 15, 2003

TO: King County International Airport Tenants
distributed by e-mail and fax

FROM: 
Robert I. Burke, Airport Director

SUBJECT: Runway 13R/31L Partial Closure - May 17 (Saturday)

KCIA will be "grooving" the section of Runway 13R/31L that was repaved at the end of April. This area is located between the B3 and B4 taxiway intersections.

The grooving is scheduled for **May 17, 2003 - SATURDAY from 0830 - 2030 local time**. This project will not be weather dependent. It will require **closing the north 5000 feet of RWY 13R**. Therefore, if 13R is active, there will be 5000 feet for arrival and departure. If 31L is active, there will be 5000 feet for departure and 4200 feet for arrival. Additionally, the **B3 and B2 taxiway intersections will be closed**. Be sure to **CHECK NOTAMs** for any changes.

We apologize for any inconvenience the repairs to the main runway have caused over the past few weekends, but we are sure you will be pleased with

*** TX REPORT ***

TRANSMISSION OK


TX/RX NO	3215	
CONNECTION TEL		97625732
SUBADDRESS		
CONNECTION ID		
ST. TIME	05/16 07:28	
USAGE T	00'49	
PGS. SENT	1	
RESULT	OK	



KCIA AIRPORT ADVISORY

DATE: May 15, 2003

TO: King County International Airport Tenants
distributed by e-mail and fax

FROM: 
Robert I. Burke, Airport Director

SUBJECT: Runway 13R/31L Partial Closure - May 17 (Saturday)

KCIA will be "grooving" the section of Runway 13R/31L that was repaved at the end of April. This area is located between the B3 and B4 taxiway intersections.

The grooving is scheduled for **May 17, 2003 - SATURDAY from 0830 - 2030 local time**. This project will not be weather dependent. It will require **closing the north 5000 feet of RWY 13R**. Therefore, if 13R is active, there will be 5000 feet for arrival and departure. If 31L is active, there will be 5000 feet for departure and 4200 feet for arrival. Additionally, the **B3 and B2 taxiway intersections will be closed**. Be sure to **CHECK NOTAMs** for any changes.

We apologize for any inconvenience the repairs to the main runway have caused over the past few weekends, but we are sure you will be pleased with the improved runway surface.

*** TX REPORT ***

TRANSMISSION OK

TX/RX NO	3214	
CONNECTION TEL		97671550
SUBADDRESS		
CONNECTION ID		
ST. TIME	05/16 07:27	
USAGE T	00'27	
PGS. SENT	1	
RESULT	OK	



KCLIA AIRPORT ADVISORY

DATE: May 15, 2003

TO: King County International Airport Tenants
distributed by e-mail and fax

FROM: 
Robert I. Burke, Airport Director

SUBJECT: Runway 13R/31L Partial Closure - May 17 (Saturday)

KCLIA will be "grooving" the section of Runway 13R/31L that was repaved at the end of April. This area is located between the B3 and B4 taxiway intersections.

The grooving is scheduled for **May 17, 2003 - SATURDAY from 0830 - 2030 local time**. This project will not be weather dependent. It will require **closing the north 5000 feet of RWY 13R**. Therefore, if 13R is active, there will be 5000 feet for arrival and departure. If 31L is active, there will be 5000 feet for departure and 4200 feet for arrival. Additionally, the **B3 and B2 taxiway intersections will be closed**. Be sure to **CHECK NOTAMs** for any changes.

We apologize for any inconvenience the repairs to the main runway have caused over the past few weekends, but we are sure you will be pleased with

*** TX REPORT ***

TRANSMISSION OK

TX/RX NO 3213
CONNECTION TEL 97680483
SUBADDRESS
CONNECTION ID
ST. TIME 05/16 07:25
USAGE T 02'14
PGS. SENT 1
RESULT OK



KCIA AIRPORT ADVISORY

DATE: May 15, 2003

TO: King County International Airport Tenants
distributed by e-mail and fax

FROM: 
Robert I. Burke, Airport Director

SUBJECT: Runway 13R/31L Partial Closure - May 17 (Saturday)

KCIA will be "grooving" the section of Runway 13R/31L that was repaved at the end of April. This area is located between the B3 and B4 taxiway intersections.

The grooving is scheduled for **May 17, 2003 - SATURDAY from 0830 - 2030 local time**. This project will not be weather dependent. It will require **closing the north 5000 feet of RWY 13R**. Therefore, if 13R is active, there will be 5000 feet for arrival and departure. If 31L is active, there will be 5000 feet for departure and 4200 feet for arrival. Additionally, the **B3 and B2 taxiway intersections will be closed**. Be sure to **CHECK NOTAMs** for any changes.

We apologize for any inconvenience the repairs to the main runway have caused over the past few weekends, but we are sure you will be pleased with

*** TX REPORT ***

TRANSMISSION OK

TX/RX NO	3220
CONNECTION TEL	94253937741
SUBADDRESS	
CONNECTION ID	
ST. TIME	05/16 07:36
USAGE T	00'33
PGS. SENT	1
RESULT	OK



KCIA AIRPORT ADVISORY

DATE: May 15, 2003

TO: King County International Airport Tenants
distributed by e-mail and fax

FROM: 
Robert I. Burke, Airport Director

SUBJECT: Runway 13R/31L Partial Closure - May 17 (Saturday)

KCIA will be "grooving" the section of Runway 13R/31L that was repaved at the end of April. This area is located between the B3 and B4 taxiway intersections.

The grooving is scheduled for **May 17, 2003 - SATURDAY from 0830 - 2030 local time**. This project will not be weather dependent. It will require **closing the north 5000 feet of RWY 13R**. Therefore, if 13R is active, there will be 5000 feet for arrival and departure. If 31L is active, there will be 5000 feet for departure and 4200 feet for arrival. Additionally, the **B3 and B2 taxiway intersections will be closed**. Be sure to **CHECK NOTAMs** for any changes.

We apologize for any inconvenience the repairs to the main runway have caused over the past few weekends, but we are sure you will be pleased with

*** TX REPORT ***

TRANSMISSION OK

TX/RX NO	3219	
CONNECTION TEL		97675604
SUBADDRESS		
CONNECTION ID		
ST. TIME	05/16 07:34	
USAGE T	01'02	
PGS. SENT	1	
RESULT	OK	



KCIA AIRPORT ADVISORY

DATE: May 15, 2003

TO: King County International Airport Tenants
distributed by e-mail and fax

FROM: 
Robert I. Burke, Airport Director

SUBJECT: Runway 13R/31L Partial Closure - May 17 (Saturday)

KCIA will be "grooving" the section of Runway 13R/31L that was repaved at the end of April. This area is located between the B3 and B4 taxiway intersections.

The grooving is scheduled for **May 17, 2003 - SATURDAY from 0830 - 2030 local time.** This project will not be weather dependent. It will require **closing the north 5000 feet of RWY 13R.** Therefore, if 13R is active, there will be 5000 feet for arrival and departure. If 31L is active, there will be 5000 feet for departure and 4200 feet for arrival. Additionally, the **B3 and B2 taxiway intersections will be closed.** Be sure to **CHECK NOTAMs** for any changes.

We apologize for any inconvenience the repairs to the main runway have caused over the past few weekends, but we are sure you will be pleased with

KCSlip4 34414

SEA400961

*** TX REPORT ***

TRANSMISSION OK

TX/RX NO 3218
CONNECTION TEL 97640142
SUBADDRESS
CONNECTION ID
ST. TIME 05/16 07:32
USAGE T 01'36
PGS. SENT 1
RESULT OK



KCLIA AIRPORT ADVISORY

DATE: May 15, 2003

TO: King County International Airport Tenants
distributed by e-mail and fax

FROM: 
Robert I. Burke, Airport Director

SUBJECT: Runway 13R/31L Partial Closure - May 17 (Saturday)

KCIA will be "grooving" the section of Runway 13R/31L that was repaved at the end of April. This area is located between the B3 and B4 taxiway intersections.

The grooving is scheduled for **May 17, 2003 - SATURDAY** from **0830 - 2030 local time**. This project will not be weather dependent. It will require **closing the north 5000 feet of RWY 13R**. Therefore, if 13R is active, there will be 5000 feet for arrival and departure. If 31L is active, there will be 5000 feet for departure and 4200 feet for arrival. Additionally, the **B3 and B2 taxiway intersections will be closed**. Be sure to **CHECK NOTAMs** for any changes.

We apologize for any inconvenience the repairs to the main runway have caused over the past few weekends, but we are sure you will be pleased with

*** TX REPORT ***

TRANSMISSION OK

TX/RX NO 3221
CONNECTION TEL 97671726
SUBADDRESS
CONNECTION ID
ST. TIME 05/16 07:37
USAGE T 02'17
PGS. SENT 1
RESULT OK



KCIA AIRPORT ADVISORY

DATE: May 15, 2003

TO: King County International Airport Tenants
distributed by e-mail and fax

FROM: 
Robert I. Burke, Airport Director

SUBJECT: Runway 13R/31L Partial Closure - May 17 (Saturday)

KCIA will be "grooving" the section of Runway 13R/31L that was repaved at the end of April. This area is located between the B3 and B4 taxiway intersections.

The grooving is scheduled for **May 17, 2003 - SATURDAY from 0830 - 2030 local time**. This project will not be weather dependent. It will require **closing the north 5000 feet of RWY 13R**. Therefore, if 13R is active, there will be 5000 feet for arrival and departure. If 31L is active, there will be 5000 feet for departure and 4200 feet for arrival. Additionally, the **B3 and B2 taxiway intersections will be closed**. Be sure to **CHECK NOTAMs** for any changes.

We apologize for any inconvenience the repairs to the main runway have caused over the past few weekends, but we are sure you will be pleased with

KCSlip4 34416

SEA400963

*** TX REPORT ***

TRANSMISSION OK

TX/RX NO 3223
CONNECTION TEL 97621561
SUBADDRESS
CONNECTION ID
ST. TIME 05/16 07:41
USAGE T 01'23
PGS. SENT 1
RESULT OK



KCIA AIRPORT ADVISORY

DATE: May 15, 2003

TO: King County International Airport Tenants
distributed by e-mail and fax

FROM: 
Robert I. Burke, Airport Director

SUBJECT: Runway 13R/31L Partial Closure - May 17 (Saturday)

KCIA will be "grooving" the section of Runway 13R/31L that was repaved at the end of April. This area is located between the B3 and B4 taxiway intersections.

The grooving is scheduled for **May 17, 2003 - SATURDAY from 0830 - 2030 local time**. This project will not be weather dependent. It will require **closing the north 5000 feet of RWY 13R**. Therefore, if 13R is active, there will be 5000 feet for arrival and departure. If 31L is active, there will be 5000 feet for departure and 4200 feet for arrival. Additionally, the **B3 and B2 taxiway intersections will be closed**. Be sure to **CHECK NOTAMs** for any changes.

We apologize for any inconvenience the repairs to the main runway have caused over the past few weekends, but we are sure you will be pleased with

KCSlip4 34417

SEA400964

*** TX REPORT ***

TRANSMISSION OK

TX/RX NO 3222
CONNECTION TEL 97673367
SUBADDRESS
CONNECTION ID
ST. TIME 05/16 07:39
USAGE T 00'40
PGS. SENT 1
RESULT OK



KCIA AIRPORT ADVISORY

DATE: May 15, 2003

TO: King County International Airport Tenants
distributed by e-mail and fax

FROM: Robert I. Burke, Airport Director

SUBJECT: Runway 13R/31L Partial Closure - May 17 (Saturday)

KCIA will be "grooving" the section of Runway 13R/31L that was repaved at the end of April. This area is located between the B3 and B4 taxiway intersections.

The grooving is scheduled for **May 17, 2003 - SATURDAY from 0830 - 2030 local time**. This project will not be weather dependent. It will require **closing the north 5000 feet of RWY 13R**. Therefore, if 13R is active, there will be 5000 feet for arrival and departure. If 31L is active, there will be 5000 feet for departure and 4200 feet for arrival. Additionally, the **B3 and B2 taxiway intersections will be closed**. Be sure to **CHECK NOTAMs** for any changes.

We apologize for any inconvenience the repairs to the main runway have caused over the past few weekends, but we are sure you will be pleased with the improved runway surface.

KCSlip4 34418

SEA400965